


ALIO PRO

APRD-02i FOR DALI SENSORS




GB MANUAL

IR REMOTE CONTROL FOR DALI SENSORS


ON	Load switching ON		Automatic read-in of actual light level
OFF	Load switching OFF (Sensor unworkable)	10 LUX ~ 2000 LUX	Adjust LUX value from 10-2000LUX
AUTO	Automatic mode	10 SEC ~ 30 MIN	Set delay off time of load
RESET	Sensor responds according to knob setting (Erasing all settings)	DIM  DIM 	Adjust the brightness of the load
	Key unlock / Key lock	STBY 5MIN ~ STBY ∞	Load on time in standby mode
TEST	Test mode	STBY OFF	Load on time in standby mode
DA1 DA2	Channel 1 / Channel 2 selection	STBY 10% STBY 20% STBY 30%	Load on illumination in standby mode
A/M	Automatic / Semi-Automatic mode selection		

BATTERY REPLACEMENT

1 Pull out the battery holder



2 Put in a new battery (3V)



BATTERY NOT INCLUDED IN THE SET



SIA PAWBOL Baltic
Reg. Nr: 40103888768
VAT: Nr LV40103888768
Katiakalna 9A, Riga, Latvia, LV1073
Phone: + 371 62006800
Email: info@vexen.eu

vexen
electric

WWW.VEXEN.EU

Manufactured in PRC